

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>JANUARY 29, 2007</b>			
M05-141	Mark Farrar Nonregistrant	<p>On or about October 27, 2004, Respondent's firm, "Clyde's CAD &amp; Design," advertised in the 2004 Flagstaff Dex yellow pages under the heading of "Architects" as an Architectural firm providing "residential and commercial designs" and at the firm's website, www.clydescad.com. Respondent advertised and offered architectural and structural engineering services without the benefit of registration.</p> <p>On or about March 26, 2006, Respondent started "Clyde's Civil and Architecture, Inc." Respondent offered architectural, engineering and surveying services without the benefit of registration.</p>	<p><b>Assurance of Discontinuance</b> – Respondent shall not practice, offer to practice, or by any implication hold himself out as qualified to practice Architecture, Professional Engineering and/or Land Surveying, as defined by A.R.S. §§ 32-101(B)(2) and (4), -101(B)(11) and (12) and -101(B)(22) and (23); shall not advertise or display any card, sign or other device that may indicate to the public that he is a Registered Architect, Professional Engineer, or Registered Land Surveyor, or is qualified to practice as such within the State of Arizona until Respondent is granted registration by the Board.</p> <p><b>Civil Penalty</b> – Pay a civil penalty of \$2,000.00.</p> <p><b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$155.00.</p>
M06-202	Justin T. Supanich Nonregistrant	On or about November 5, 2005, Respondent conducted a survey and prepared a survey map that constituted the practice of land surveying by making measurements of land to determine the position of property monuments and platting the results of these measurements.	<p><b>Assurance of Discontinuance</b> – Respondent shall not practice, offer to practice, or by any implication hold himself out as qualified to practice Land Surveying, as defined by A.R.S. §§ 32-101(B)(22) and (23) within the State of Arizona until Respondent is granted registration by the Board.</p> <p><b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$80.00.</p>
M05-267	James J. O'Connor Land Surveyor #30361	On or about August 23, 2002, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent prepared a Record of Survey and a Minor Land Division that are deficient in that Respondent failed to show sufficient mathematical ties to controlling monuments, failed to show bearing and distances to the East Quarter corner, failed to list pertinent documents used during the retracement of the survey, and failed to set a properly identified monument at the Center Quarter corner of Section 28.	<p><b>Letter of Reprimand</b></p> <p><b>Probation: Amend Survey</b> – Respondent shall prepare an Amended Record of Survey, submit it to the Board for review and approval, and record it with the Pinal County Recorder's Office.</p> <p><b>Cost of Investigation</b> Pay cost of investigation in the amount of \$215.00.</p>
M06-319	Stan G. Faris Land Surveyor #35235	On or about April 18, 2003 and September 7, 2004, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent prepared a Record of Survey and a Revised Record of Survey that are deficient in that Respondent failed to identify on his survey maps points set in the field, failed to set sufficient monuments, and failed to set section corners used to re-establish lines pertinent to his survey.	<p><b>Letter of Reprimand</b></p> <p><b>Probation: Amend Survey</b> – Respondent shall prepare an Amended Record of Survey, submit it to the Board for review and approval, and record it with the Pinal County Recorder's Office.</p> <p><b>Cost of Investigation</b> Pay cost of investigation in the amount of \$175.00.</p>
M06-210	Earl F. McKinney P.E. (Mechanical) #12765 P.E. (Electrical) #29966	On or about November 16, 2005, Respondent's Kentucky Professional Registration No. 05589 was revoked by the Kentucky Board. The Arizona Board took action based on the Kentucky Board's revocation of Respondent's Kentucky engineer registration for the signing and sealing of numerous plans without adequate review.	<b>Revocation</b> of Respondent's P.E. (Mechanical) Registration No. 12765 and P.E. (Electrical) Registration No. 29966.

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>FEBRUARY 27, 2007</b>			
M05-084	John G. Light Land Surveyor #24525	On or about April 24, 2003, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent located the corners of the property, found monuments not of record and showed relationships in the field. Respondent failed to prepare a scope of services; failed to identify measurement ties to controlling monuments and existing improvements; and failed to prepare a Results of Survey and record the survey with the Cochise County Recorder's Office.	<b>Letter of Reprimand</b> <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$450.00.
M05-413	Thomas B. Hollenbach Land Surveyor #17278	On or about March 2005, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent prepared an ALTA/ACSM Land Title Survey that was deficient in that Respondent failed to have a scope of services; failed to show physical features on the site or adjoining the site; failed to show the paved access roads with the curbs on the west part of the site; and used the 1999 ALTA Standards and incorrectly referenced Urban Classification.	<b>Letter of Reprimand</b> <b>Professional Education</b> – Respondent shall attend an ALTA/ACSM Survey Standards Seminar. <b>Peer Review</b> of three (3) ALTA/ACSM survey projects. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$185.00.
M06-269	Allan Lee Gray Land Surveyor #31595	On or about September 2003, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area at the same time and failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent failed to accurately stake the front two corners of the lot. The owners relied on Respondent's stakes for construction of a house. After construction, it was discovered the house encroached onto the adjacent property. Respondent failed to prepare a Record of Survey and failed to record the survey with the Coconino County Recorder's Office.	<b>Letter of Reprimand</b> <b>Peer Review</b> of Respondent's next three (3) boundary surveys. <b>Examination</b> – Respondent shall take and successfully complete the three (3) hour Arizona State Specific Exam for Land Surveyors administered by Board staff. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$230.00.

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>MARCH 27, 2007</b>			
M06-235	Applied Envirosolutions, Inc.	On or about December 2005 through May 2006, Respondent firm offered engineering and/or geological services in the State of Arizona without being registered by the Board. Respondent firm advertised on their website that they could provide engineering services. Respondent firm prepared a Site Characterization Work Plan that included technical information, interpretations and recommendations which constitutes the practice of engineering and/or geology. (Respondent firm is currently registered.)	<b>Administrative Penalty</b> – Pay an administrative penalty of \$750.00. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$410.00.
M06-180 M06-224	Victor G. Story Land Surveyor #33326	On or about December 2004, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area at the same time. Respondent's construction staking was deficient in that a portion of the sewer system for the project had to be removed and additional engineering was required for some re-design of the project.  On or about December 9, 2005, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent performed a Parcel Split and a Lot Line Adjustment that is deficient in that Respondent failed to provide the correct distance along the west line of the Northwest quarter of Section 2; failed to tie to all the controlling monuments and adjacent properties of the aliquot calls in the deed; failed to properly breakout the section and verify the adjacent property corners; failed to provide descriptions of what was found or set in the field.	<b>Letter of Reprimand</b> <b>Administrative Penalty</b> – Pay an administrative penalty of \$500.00. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$510.00.
M02-032 M05-417 M05-332 M06-234 M04-054 M07-082	Charles E. Martin P.E. (Civil) #05968 Land Surveyor #16162	The Board alleges that on or about September 2000 and July 2001, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area at the same time. The Board alleges that Respondent prepared engineering plans that were deficient and incorrect in a material manner.  The Board alleges that on or about July 2001 through March 2003 and April 11, 2005, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards by preparing surveys that were deficient and incorrect in a material manner.	<b>Examinations</b> – In 2007, Respondent shall take and successfully complete the following examinations: <ul style="list-style-type: none"> <li>• The NCEES Principles and Practice of Engineering (Civil) Examination.</li> <li>• The NCEES Principles and Practice of Surveying Examination.</li> <li>• The three (3) hour Arizona State Specific Examination for Land Surveyors.</li> <li>• If Respondent fails the examinations, Respondent's registration in that category of registration shall be suspended until Respondent successfully passes the Examinations.</li> </ul> <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$2,130.00.

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>APRIL 27, 2007</b>			
M05-199	Lloyd W. Rogers P.E. (Civil) #17927	On or about March 2, 2002, August 29, 2003 and February 11, 2004, Respondent prepared soil evaluations for three (3) properties that were deficient. Respondent mischaracterized the actual soil conditions relating to the soil type and the per cent of rock fragments where the disposal trenches were constructed.	<b><i>Letter of Reprimand</i></b> <b><i>Professional Education</i></b> – Respondent shall take and successfully complete six (6) hours of professional courses in the area of soils evaluations. <b><i>Peer Review</i></b> of Respondent's next three (3) soil evaluations. <b><i>Cost of Investigation</i></b> – Pay cost of investigation in the amount of \$660.00.
M06-078	Henry A. Shearrow Land Surveyor #09087	On or about August 1, 2005, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent performed a survey and prepared a parcel split. Respondent's parcel split map is deficient in that Respondent failed to indicate the controlling monuments for the basis of bearing in the new legal descriptions, failed to include all symbols and abbreviations used in the legend, and failed to indicate the central angle on the curve annotation along the eastern line of Parcel B; failed to indicate if the found monuments are on the mid-section line; failed to indicate the recording information for the existing easements and failed to indicate the thirty foot (30') drainage easement along the southwestern line of Parcel A as existing or proposed; and failed to note any documents or surveys by others that would substantiate the boundary lines or found monuments that the survey was based on.	<b><i>Letter of Reprimand</i></b> <b><i>Cost of Investigation</i></b> – Pay cost of investigation in the amount of \$545.00.
M07-011	Geoffrey K. Brimhall Land Surveyor #33308	Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. On or about August, 2002, Respondent prepared and sealed a Boundary & Topo Map that was deficient in that Respondent failed to provide ties to controlling monuments so that the survey may be retraced; failed to show a basis of bearing; failed to include a surveyor's statement that the survey was performed by the surveyor or under his direct supervision; and failed to include a legend. On or about September 7, 2006, Respondent prepared an Amended Boundary & Topo Map for the project that is deficient in that Respondent failed to show a basis of bearing; failed to include a surveyor's statement that the survey was performed by the surveyor or under his direct supervision; and failed to record the amended survey with the Pima County Recorder's Office.	<b><i>Letter of Reprimand</i></b> <b><i>Amend Survey</i></b> – Respondent shall prepare and record an amended survey. <b><i>Cost of Investigation</i></b> – Pay cost of investigation in the amount of \$120.00

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>MAY 22, 2007</b>			
M06-057 M06-072 M06-086	Frank E. Junkar Nonregistrant <i>and</i> A1 ALTA Land Surveyors & Engineers ("Firm")	<p>On or about May 2005 through September 2005, the Firm provided professional engineering and land surveying services in the State of Arizona without being registered by the Board. During that time, the Firm did not have a registrant as the principal and responsible registrant for the firm. Respondent was the owner of the Firm and a nonregistrant.</p> <p>On or about November 2005, Respondent distributed business cards to the public that listed "Frank Yunkar, President, General Manager, R.L.S. 5523" without the Respondent being registered by the Board.</p>	<p><b>Civil Penalty</b> – Pay a civil penalty of \$1,000.00.</p> <p><b>Surveying Examinations</b> – Respondent shall take and successfully pass the following surveying examinations in 2007:</p> <ul style="list-style-type: none"> <li>• NCEES Principles and Practice of Surveying Examination.</li> <li>• The three (3) hour Arizona State Specific Examination for Land Surveyors.</li> </ul> <p>If Respondent fails an examination, Respondent shall not be a principal or owner of an engineering and/or land surveying firm. Respondent shall not practice, offer to practice, or by any implication hold himself out as qualified to practice professional engineering or professional land surveying in Arizona as defined by A.R.S. § 32-101(B)(22) and (23).</p> <p><b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$850.00.</p>
M06-158	Anthony N. Zaugg Land Surveyor #41076	<p>Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area at the same time; and Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards.</p> <ul style="list-style-type: none"> <li>• On or about November 5, 2004, Respondent performed a survey and prepared a Results of Survey. Respondent's survey was deficient in that Respondent failed to obtain and examine the record documents needed to perform the survey; failed to search for physical evidence that affect the location and/or placement of boundary lines and property corners of the property; failed to search for and tie pertinent 1/16<sup>th</sup> and 1/64<sup>th</sup> corners that would affect the property location; and failed to list pertinent reference documents that were used as a basis for the survey.</li> <li>• On or about February 7, 2006, Respondent prepared an ALTA survey that is deficient in that Respondent failed to list pertinent reference documents that were used as a basis for his survey; and failed to note or make statement of conclusions as to decisions made in location of the title lines and corners of ownership.</li> </ul>	<p><b>Letter of Reprimand</b></p> <p><b>Professional Education</b> – Respondent shall take and successfully complete six (6) credit hours of professional surveying courses.</p> <p><b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$435.00.</p>
M07-044	Vernon Q. Jones Land Surveyor #06851	<p>On or about October 17, 2006, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent provided surveying services to locate property lines that are deficient in that Respondent failed to set permanent survey markers at the property corners; failed to provide his client with a survey map; and failed to record the survey.</p>	<p><b>Professional Education</b> – Respondent shall take and successfully complete six (6) credit hours of professional surveying courses.</p> <p><b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$185.00.</p>

M07-065	Stanford L. Brody Nonregistrant	On or about December 2006, Respondent prepared electrical and mechanical engineering plans and submitted the plans to the City of Tempe for review and approval. Respondent sealed the plans with fraudulent seals and fraudulent registration numbers that listed Stanford L. Brody, P.E. (Mechanical) No. 35541 and Stanford L. Brody, P.E. (Electrical) No. 26734.	<p><b><i>Assurance of Discontinuance</i></b> – Respondent shall not practice, offer to practice, or by any implication hold himself out as qualified to practice Engineering, as defined by A.R.S. §§ 32-101(B)(11) and (12); shall not advertise or display any card, sign or other device that may indicate to the public that he is a registered Professional Engineer, or is qualified to practice as such; and shall not assume the title of "Professional", "P.E.", "Registered", "Registered Professional", or "Professional Registered" Engineer within the State of Arizona until Respondent is granted registration by the Board as required by A.R.S. § 32-121.</p> <p><b><i>Civil Penalty</i></b> – Pay a civil penalty of \$5,000.00.</p> <p><b><i>Cost of Investigation</i></b> – Pay cost of investigation in the amount of \$200.00.</p>
---------	------------------------------------	---	--

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>JULY 24, 2007</b>			
M06-096	Richard G. Kelly P.E. (Civil) #26853	Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. On or about March 2002, Respondent prepared a Subsurface Soil Exploration; and on or about April 2002, Respondent prepared an Addendum to the report. Respondent's work was deficient in that the field exploration program did not generate the quantitative information that is typically collected by geotechnical consultants when performing pre-construction geotechnical evaluations; and the work did not include laboratory testing for moisture density, swell testing, and compression consolidation testing.	<b>Letter of Reprimand</b> <b>Professional Education</b> – Respondent shall take and successfully complete a course in the area of geotechnical engineering. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$670.00.
M06-272	Clifford Don Walding Land Surveyor #33880	On or about April 2005, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent prepared a Results of Survey map which is deficient in that Respondent failed to include the required surveyor's statement; failed to explain in detail the reason for not accepting a monument; failed to indicate the record documents referenced where there were differences in the record and measured bearings and distances; failed to secure his RLS number on identifying markers on recovered monumentation that was not tagged or marked; and failed to record the survey in the Maricopa County Recorder's Office after setting new monuments.	<b>Letter of Reprimand</b> <b>Amend Survey</b> – Respondent shall amend his survey and record it with the Maricopa County Recorder's Office. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$215.00.
M07-007	James D. Downing P.E. (Agricultural) #19202	On or about October 2003, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent prepared As Built Drawings and sealed an Engineer's Certificate of Completion and Final Inspection ("ECC") for a water distribution system which were deficient in that Respondent failed to note that the completed project deviated from the plans which received the Approval to Construct; and failed to indicate that the space layout was not consistent with the approved plans.  On or about February 2006, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent prepared and sealed As Built plans for a drinking water system which were deficient in that Respondent failed to accurately reflect the system that was constructed and failed to submit accurate information regarding the actual well that was constructed.	<b>Letter of Reprimand</b> <b>Administrative Penalty</b> – Pay an administrative penalty of \$1,500.00. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$490.00.
M07-062	Felix G. Steele Land Surveyor #28234	On or about December 2005, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent performed and prepared a Record of Survey that is deficient in that Respondent failed to show an encroachment of a barn/shed onto the southeast boundary of the property.	<b>Letter of Reprimand</b> <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$125.00.

M06-318 M06-146 M06-155	George H. Baker Architect #11374	<p>Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time.</p> <ul style="list-style-type: none"> <li>• On or about September 2002, Respondent sealed a site plan for a vision center that is deficient in that Respondent failed to provide correct drainage for the site plan and failed to research and show the correct number of parking spaces on the site plan.</li> <li>• On or about December 2004, Respondent sealed plans for a single family remodel and detached garage that are deficient in that Respondent failed to place the detached garage within the required setbacks and distance from the house; failed to show on his detail sheets anchors at the foundation or the roof structure of the rear patio; failed to show what part of the covered entry is new and what was existing and how they were attached; and failed to coordinate between the new garage sheet section and the other sheets</li> <li>• On or about March 29, 2005, Respondent sealed plans for a renovation of a building that are deficient in that Respondent failed to provide an accessible route to the second floor area consisting of an accessible ramp or elevator; failed to provide numerous accessibility designs for the disabled; failed to provide coordination between the structural details and the architectural plans; and failed to coordinate the site plan and the grading and drainage plan as it relates to the sewer lines.</li> </ul>	<p><b>Suspension</b> – Respondent’s Registered Architect Registration No. 11374 shall be suspended for a period of six (6) months. The suspension shall be effective from January 1, 2008 through June 30, 2008.</p> <p><b>Administrative Penalty</b> – Pay an administrative penalty of \$1,000.00.</p> <p><b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$1,600.00.</p>
M07-041	Eric W. Sparkman P.E. (Civil) #34021	<p>On or about June 2006, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent prepared and certified Grading and Drainage As Built plans that were deficient in that Respondent certified that the grading and drainage was constructed according to the approved plans and failed to accurately depict what was actually built. Respondent failed to review and field verify the as built plans; failed to indicate whether or not the berms, the valley gutters, and the high point asphalt grade break were installed to specifications; failed to certify that the required retention volumes had been provided; and failed to indicate changes to the elevations of the south and west basins with the approved design plans.</p>	<p><b>Letter of Reprimand</b></p> <p><b>Administrative Penalty</b> – Pay an administrative penalty of \$2,000.00.</p> <p><b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$415.00.</p>



Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>AUGUST 28, 2007</b>			
M05-396	Crystal F. Pearl Architect #36012	On or about September 30, 2004, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent failed to submit plans to the City Planning and Zoning Department for review, comments and pre-approval before proceeding to construction drawings. Respondent failed to obtain prerequisite information before proceeding with the construction documents and failed to obtain an A.L.T.A. Survey and civil engineering for grading and drainage plans. Respondent's design plans for the building expansion were deficient in that Respondent failed to apply correct building and landscape setbacks; failed to coordinate the building's location between the site plans and civil plans; failed to show correct exterior elevations; and failed to comply with ADA requirements.	<b>Suspension</b> – Respondent's Registered Architect Registration No. 36012 shall be suspended for six (6) months or until restitution is paid, whichever is the longer. <b>Probation</b> – Respondent's Registered Architect Registration No. 36012 shall be placed on probation until Respondent pays restitution.
M05-174 M06-293	Raad M. Salih P.E. (Civil) #34016	Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. <ul style="list-style-type: none"> <li>On or about February 6, 2004, Respondent prepared grading and drainage plans that were deficient in that Respondent failed to use the correct benchmark and county datum and failed to show correct contour lines for the existing fill slopes on the westerly side of the access road and other areas of the site. Respondent's grading and drainage plans are inconsistent in that the property line bearings and distances are not consistent with the Lot Closure. Respondent submitted grading and drainage plans to his client and failed to sign, date, and seal it or mark it "preliminary," "draft," or "not for construction."</li> <li>On or about April 4, 2004, Respondent prepared a Drainage Report that is deficient in that Respondent failed to provide information regarding the offsite drainage coming onto the lot and failed to provide information as to the minimum finished floor elevation. On or about June 21, 2005, Respondent prepared grading &amp; drainage plans that are deficient in that Respondent failed to show sufficient existing grades along the street to set the correct finished floor elevations and failed to provide sufficient grades next to the house.</li> </ul>	<b>Letter of Reprimand</b> <b>Peer Review</b> of Respondent's next two (2) grading and drainage projects. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$1,215.00.

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>OCTOBER 23, 2007</b>			
M07-072	Timothy M. O'Neill Land Surveyor #17403	On or about May 2004 and October 2006, Respondent prepared and sealed ALTA/ACSM surveys for the Tucson International Gateway Center and failed to record a Results of Survey with the Pima County Recorder's Office in the required time.	<b>Letter of Reprimand</b> <b>Probation</b> – Respondent's Land Surveyor Registration No. 17403 shall be placed on probation until Respondent records a Results of Survey of Lots 11-14 of the Tucson International Gateway Center with the Pima County Recorder's Office. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$160.00.
M08-042	O'Neill Engineering, Inc.	On or about September 2004 through March 4, 2007, Respondent Firm provided engineering and land surveying services in the State of Arizona without registration.	<b>Administrative Penalty</b> – Pay an administrative penalty of \$1,000.00. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$75.00.
M07-120	Innovative Earthworks, Inc.	On or about June 2006 through July 30, 2007, Respondent Firm provided engineering services in the State of Arizona without registration.	<b>Administrative Penalty</b> – Pay an administrative penalty of \$500.00. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$75.00.
M07-074	William J. Christenson P.E. (Structural) #34626	On or about June 2005, Respondent conducted a site inspection and prepared a report of the structural inspection of the residence foundation walls. Respondent failed to apply the technical knowledge and skill which would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent's June 2005 Report was deficient in that Respondent failed to indicate that the lateral walls are not supported at the top; that perpendicular blocking was not used; and that the walls were not evaluated as cantilevered walls. Respondent failed to use lateral earth loads in his calculations of the walls; failed to verify the rebar sizes and location of the rebar in the walls; and failed to determine the correct water source as it relates to the walls in that the water is not being directed away from the foundation walls.	<b>Letter of Reprimand</b> <b>Peer Review</b> – Peer review of Respondent's next three (3) structural projects having basements. <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$675.00.
M06-160	Terry L. Moore P.E. (Civil) #09293	On or about August 4, 2005, Respondent sealed an Engineer's Certificate of Completion, knowing that it was not correct at the time he sealed it, and failed to apply the technical knowledge and skill which would be applied by other qualified registrants who practice the same profession in the same area and at the same time.	<b>Letter of Reprimand</b> <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$235.00.

M05-308 M05-326 M06-157 M06-175 M06-214 M06-274 M06-284 M06-285 M07-033 M07-035 M07-057 M07-075 M07-109	Thomas H. Trimble P.E. (Civil) #15620 Land Surveyor #15343	<p>Respondent failed to apply the technical knowledge and skill which would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent prepared engineering plans and surveys that were incomplete and/or contained errors; failed to complete the engineering and land surveying services; and failed to provide clients with plans.</p> <p>On or about May 18, 2006, after receiving payment from his client, Respondent failed to pay a collaborating registered professional in the required time.</p>	<p><b><i>Suspension</i></b> – Respondent’s Arizona Registered P.E. (Civil) No. 15620 registration and Arizona Registered Land Surveyor No. 15343 registration shall be suspended for a period of one (1) year.</p> <p><b><i>Probation</i></b> – Respondent’s Professional Engineer (Civil) Registration No. 15620 and Land Surveyor Registration No. 15343 shall be placed on probation for two (2) years following the one (1) year suspension. The terms and conditions of probation are as follows:</p> <p>a. <b><i>Administrative Penalty</i></b> – Pay an administrative penalty of \$5,000.00.</p> <p>b. <b><i>Peer Review</i></b> – Following Respondent’s one (1) year suspension, Respondent shall submit all engineering and surveying projects to a peer reviewer for a twelve (12) month period.</p> <p><b><i>Cost of Investigation</i></b> – Pay cost of investigation in the amount of \$2,240.00.</p>
---	--	--	--

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>NOVEMBER 27, 2007</b>			
M05-227 M06-271	Philip Wayne Rosendahl P.E. (Civil) #24718 Land Surveyor #24532	<p>On or about January 1997 to October 1998, Respondent allowed his seal and signature to be applied to approximately seven (7) building pad compaction reports and failed to review the building pad compaction reports before they were provided to the client.</p> <p>On or about January 1997 through May 1998, Respondent prepared Geotechnical Subsoil Investigation Reports for various commercial projects that are deficient. Respondent failed to perform field tests to identify engineering properties of the insitu soils; failed to perform adequate laboratory testing to determine engineering properties of the soils; failed to provide anticipated building loads and failed to provide recommendations for repairing site soils disturbed by the excavation of exploratory test pits.</p> <p>On or about October 29, 1998, Respondent prepared a Geotechnical Subsoil Investigation Report for a residential project that is deficient. Respondent failed to perform adequate laboratory testing to determine the engineering recommendations in his report with respect to foundation support, engineering properties of the soil, and the effects of wetting on foundation soils and slab-on-grade support, including site preparation and grading procedures. Respondent failed to perform field tests to identify engineering properties of the insitu soils.</p> <p>On or about October 17, 2005, Respondent prepared and sealed a Final Plat that is deficient. Respondent failed to describe existing monuments that he found and used; found and used existing monuments that were not tagged; and failed to place his Registered Land Surveyor number to the untagged monuments.</p>	<p><b>Letter of Reprimand</b>  <b>Administrative Penalty</b> – Pay an administrative penalty of \$5,000.00.  <b>Professional Education</b> – Respondent shall take and successfully complete a course in the area of geotechnical engineering.  <b>Amend Survey</b> – Respondent shall amend his survey and record it with the Maricopa County Recorder's Office.  <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$1,785.00.</p>
M07-028	AKA Architecture, LLC	On or about July 2005 through October 16, 2006, Respondent Firm provided architectural services in the State of Arizona without registration.	<p><b>Administrative Penalty</b> – Pay an administrative penalty of \$500.00.  <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$75.00.</p>
M07-093	M.E. Evans & Associates, Inc.	On or about August 2005 through April 19, 2007, Respondent Firm provided engineering services in the State of Arizona without registration.	<p><b>Administrative Penalty</b> – Pay an administrative penalty of \$800.00.  <b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$75.00.</p>

M07-097	Yurkovic Design, Inc.	On or about April 2002 through July 2004, Respondent Firm engaged in the practice of architecture by providing architectural services in the State of Arizona without registration.	<p><b><i>Assurance of Discontinuance</i></b> – Respondent Firm shall not practice, offer to practice, or by any implication hold itself out as qualified to practice Architecture as defined by A.R.S. §§ 32-101(B)(2) and (4) in the State of Arizona until Respondent Firm is registered by the Board as required by A.R.S. § 32-141.</p> <p><b><i>Civil Penalty</i></b> – Pay a civil penalty of \$2,000.00.</p> <p><b><i>Cost of Investigation</i></b> – Pay cost of investigation in the amount of \$200.00.</p>
M07-110	Shreeve GPS Services, LLC	On or about January 2007 through June 2007, Respondent Firm provided land surveying and engineering services in the State of Arizona without registration.	<p><b><i>Administrative Penalty</i></b> – Pay an administrative penalty of \$500.00.</p> <p><b><i>Cost of Investigation</i></b> – Pay cost of investigation in the amount of \$75.00.</p>

Case No.	Respondent	Summary of Findings	Summary of Board Action
<b>DECEMBER 18, 2007</b>			
M06-097	William Patrick Minette Nonregistrant	On or about May 2005, Respondent prepared hood vent and fire suppression system plans for a tenant improvement project and used the seal and signature of a registered architect on the plans without the registrant's knowledge.	<p><b>Assurance of Discontinuance</b> – Respondent shall not use a registrant's seal and signature on any document prepared by the nonregistrant.</p> <p><b>Civil Penalty</b> – Pay a civil penalty of \$2,000.00.</p> <p><b>Cost of Investigation</b> – Pay cost of investigation in the amount of \$140.00.</p>